

1. Machined surfaces  $\perp .001$  in 12"  $\parallel .002$  in 12"  $\square .001$  in 12"
2. Deburr and break all sharp edges.

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ABBOTT WORKHOLDING PRODUCTS. ANY REPRODUCTION IN PART OR WHOLE WITHOUT THE WRITTEN PERMISSION OF ABBOTT WORKHOLDING PRODUCTS IS PROHIBITED.

**Includes D1025TP Top Plate And (2) Lifting Rings Installed**

